

Price Engineering, PLLC

6221 17th Ave., Meridian, MS 39305

(601) 483-1400 (Phone/Fax)

www.priceengineering.net

PHILIP PRICE , P.E.

SUMMARY OF EXPERIENCE

Over 20 years' experience in industrial electronics and power distribution design, startup and installation supervision. Has provided forensic investigation services since 2001; covering various industrial, commercial and residential lightning and fire events.

TRAINING

- Residential Electricity for Fire Investigators – Fire Findings – 5/2009
- MFIA Fall/Spring Seminars 2006-07
- IAAI Annual Training Conference – Denver, CO 5/2006
- NTT Grounding/Bonding
- IAAI/Savannah, GA 2004 – Investigation of Electrical Appliance Related Fires
- IAAI/CFITrainer.net – Introduction to Fire Dynamics and Modeling
- IAAI/CFITrainer.net – Ethics and the Fire Investigator
- IAAI/CFITrainer.net – Digital Photography and the Fire Investigator
- IAAI/CFITrainer.net – The Scientific Method for Fire and Explosion Investigation
- IAAI/CFITrainer.net – MagneTek: A Case Study in the Daubert Challenge
- IAAI/CFITrainer.net – Analysis of the Station Nightclub Fire

PROFESSIONAL AFFILIATIONS

Registered Professional Engineer (Alabama No.21848, Mississippi No.13586)

Member – IEEE

Member - IAAI

PUBLICATIONS

Reliable Consistency Measurement w/o Rebuilding Your Pulpmill – **TAPPI Journal**, Oct. 1998

EDUCATION

B.S.E.E., University of South Alabama, 1989

Investigations – (Partial Listing)

Various, MS – Residential fire investigation for possible electrical causes (clients – Farm Bureau, State Farm, St. Paul, EMC, Firemans Fund, etc.).

Linden Lumber, Thomasville, AL – Investigated and made recommendations for remediation of multiple lightning events at central manufacturing facility.

Choctaw Maid, Philadelphia, MS – Lightning investigation at chicken houses.

Altec Lansing, Brandon, MS – Investigation into speaker system as possible cause of fire.

Alliance Healthcare Center, Union, MS – Power surge vs lightning damage to hospital equipment analysis.

Uniek Inc., Greenwood, MS – Assess lightning and fire damage to manufacturing facility electrical distribution system and recommend scope of repairs; provide cost estimate for repairs.

Tramontina, Ridgeland, MS – Investigate possible cooking pot failure as cause of fire.

Employment

Price Engineering – 1998-Present

Design Electrical Engineering and Investigative Services

Fort James (James River) - 1989-97

Group Leader, E/I Project Engineer

Alabama Power Company– 1987-88

Engineering Intern